		CONT	ROL 1		Copy 1							
	4 August 1965											
REFERRED TO	RECEIVED			RELE	ASED	SEENERY						
OFFICE	SIGNATURE	DATE	TIME	DATE	TIME	NAME & OFFICE SYMBOL DATE						
						My						
						/ / /						
		-				<u>``</u>						
					;							
						land.						
					1	·						
	••••	••••••	•••••	• • • • • • •	(1)	1 That						
					V	. X (i)						
						July William						
	••••	••••••	• • • • • • •		F*************************************							
						winter with hearter						
	••••				$I \supset I$	weiser - I'f be heart						
					00.	- If we						
iss Review by						1. if waylor						
/DOD	••••					I will but						
						. The T						
					1 (is the decision in a second						
					M	W M						
					`	in been in the front						
		WAR	NING		ĩ	W. A. A. M.						
					v							

TOP SECRET

Approved For Release 2003/01/28: GIA-RDP78B04770A002600100016-7 TOP SECRE 4 August 1965

Copy No. 1

MEMORANDUM FOR: Assistant for Plans and Development/NPIC

THROUGH:

Chief, Information Processing Division/NPIC

25X1

SUBJECT:

REFERENCE:

IPD/PRB Memo dated 2 June 1965

25X1

25X1

- 1. The Information Processing Division has been test plotting on plotter and all electronic and mechanical functions are responding satisfactorily. It was noted in the referenced memo however that the pen as far as IPD was concerned was unacceptable. The pen is still unacceptable and because of this problem full utilization of the plotter will never be realized.
- 2. The problem is solely with the pen and not with any other part of the plotter. The pen point is too broad, the ink supply is difficult and messy to work with, the pen does not draw a consistent line without skips and variations, the pen drips ink, the ink is too slow drying to use the paper feed mechanism. The above is a list of those things that IPD feels is wrong with the pen.
- 3. It is requested that P&DS obtain a more satisfactory pen and ink system as soon as possible so that early productive use of the plotter can be done.

	4.	The	<u>a</u> bo	ve pi	oblem	has	s bee	en v	/erb	al.	ly co	nve	eyed to			
														on	the	equipment
and	there	e is	no	plan	known	to	IPD	to	get	a	new	dev	rice.			

Chief, Programming Branch, IPD

Attachment: Mission Overlay

Distribution:

Original - Asst for P&DS W/att

1 - C/IPD

2 - C/PRB/IPD


089JP 1 cluded from automatic downgrading and daulassia sation





25X1

25X1

25X1







TOP SECRET